

Alert number **[SR/00847/26](#)**



Notifying country **France**

Product category **Motor vehicles**

Type **Consumer**

Product **Passenger car**

Name **Highlander**

Brand **Toyota**

EC-type approval/model **e13\*2018/858\*00028\*01 e13\*2018/858\*00028\*02  
e13\*2018/858\*00028\*03 e13\*2018/858\*00028\*04  
e6\*2018/858\*00001\*00 e6\*2018/858\*00001\*01  
e6\*2018/858\*00001\*02**

Production dates **2021 - 2023**

Company recall code **26SD-025**

Product description **Passenger car.**

Risk type **Injuries**

Risk description **The seat back of second row seats may not remain in a locked position. A seat back that has not been secured in a locked position may fail to restrain occupants properly, increasing the risk of injuries in the event of an accident.**

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

**The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

Country of origin **Luxembourg**

Measures taken by economic operators **Recall of the product from end users  
Manufacturer**

Date of entry into force **05/03/2026**

Products were found and measures were taken also in **Bulgaria  
Ireland  
Slovenia**