

Alert number

**[SR/01168/26](#)**



Notifying country **France**

Product category **Motor vehicles**

Type **Consumer**

Product **Passenger car**

Name **Combo**

Brand **Opel**

EC-type approval/model **e2\*2007/46\*0622\*31, e2\*2007/46\*0622\*32,  
e2\*2007/46\*0623\*34, e2\*2007/46\*0623\*35**

Production dates **1.10.2025 - 10.12.2025**

Company recall code **KWN**

Product description **Passenger car. VIN: W0VEDYHZ2SN565597 -  
W0VEDYHP1TN514673**

Risk type **Environment  
Fire**

Risk description **In vehicles fitted with a DV5 diesel engine, the NOx sensor may not have been properly tightened during installation. This may allow exhaust gases to enter the engine compartment and could result in visible exhaust fumes around the engine area, overheating of nearby components, a risk of fire, and increased NOx emissions.**

Legal provisions (at EU level)  
and European standards  
against which the product was

**The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.**

tested and did not comply

Country of origin

**France**

Measures taken by economic operators

**Recall of the product from end users  
Manufacturer**

Products were found and measures were taken also in

**Germany  
Slovenia**